

Volvo FM460 8x2*6, Haken



Scanvo Trucks Danmark A/S
Hårup Skovvej 7, Hårup
8600 Silkeborg

Sælger
Salgsafdeling
salg@scanvo.dk
+45 8724 4370
+45 3046 2148 / 2498 2148 / 2497 2148 / 4011 0944

Basis	
Type	Truck
Aksel	8x2*6
Stand	Fine
Registration	
Model year	2014
Reg. date	29-08-2014
Reg. no.	AC11388
Chassis number (VIN)	YV2XTY0F3EA766658
Ref. no.	7054
Engine and transmission	
Engine	12,8 Liter
Hp	460
Km	599000
Gear box	I-shift (12-trins)
EURO type	6
Number of tanks	1
Litre of tank	405
Rear axle, single interchange	✓
Ad-blue	✓
PTO engine	✓
Adblue litre of tank	64
Without clutch pedal	✓
Tyres	
% remaining	60/20 - 70/70 - 60/50 - 50/20
Dimensions	
385/65 - 385/65 - 385/65 - 315/80	R22,5
Brakes	
Disc brake	✓
ABS	✓
Engine brake	✓
Engine brake	VEB+

Cab	
Cab type	FM Globetrotter
Air-conditioning	✓
Number of sleeper berths	1
Rear-view camera	✓
Engine cab heater	✓
Equipment kit	Komfort+
Walkie	✓
Navigation	✓
Digital tachograph	✓
Cruise control	✓
Fahrhaus ausen	
Warninglight	✓
Color	Signal Green
Lightbox	✓
extra spotlights	✓
additional worklights	✓
Blitz lights	✓
Chassis	
Wheelbase mm	4900
Axle load, front kg	8500
Axle load, rear kg	7500 + 11500 + 7500
Toolbox	✓
Total length mm	8600
Liftable axles	2 + 4.
Aluminium cover	✓
Compulsive shaft	✓

Coupling	
Brand	VBG
Air-coupling	Duo-matic
Trailer hitch	✓
Air operated coupling device	✓
Coupling height mm	790
Suspension	
Front, air	✓
Rear, air	✓
Weight	
Loading capacity kg	18900
Overall weight kg	32000
Tare weight kg	13100
Hook lift	
Make	HIAB
Type	XR20SL59 - W- DC2B-
Load capacity	20
Serial number	X20SL5942530100
Model year	2014
Max container measure mm	6750 (5850 + 200 + 700)
Air intake for automatic tailgate	✓
Tippers	
Rear tipper	✓

Beskrivelse

Volvo FM460 8x4/4 - Year 2014 (Euro 6)

Built with 20-tonnes Hiab hook lift for 6750 mm containers (5850 center hook to center roller + 200 from center roller to rear edge bumper + 700 mm overhang) - Large aluminum cover - Air-operated VBG draw - Hydraulics led to rear to tip - Duomatic for aut. Tailgate

- AN OFFER YOU CAN'T REFUSE

Equipped with: Rear view camera - Extra work. lights - Flash + Rotor lights - Cruise control - Walkie - Engine cover - Air conditioning
Covered partially in yellow/black plush + Leather

Appears in good condition with hoist inspection from 04-2022



SCANVO
TRUCKS DANMARK A/S

If interested, contact us on +45 8724 4370 / salg@scanvo.dk or see our selection at www.scanvo.dk











