

Kel-Berg D23B3 5,1 mtr - 14,6m3, Tipper



Scanvo Trucks Danmark A/S
Hårup Skovvej 7, Hårup
8600 Silkeborg

Sælger
Salgsafdeling
salg@scanvo.dk
+45 8724 4370
+45 3046 2148 / +45 2498 2148

Registration	
Model year	2011
Reg. date	06-10-2011
Reg. no.	DE8822
Latest inspection	13-08-2025
Chassis number (VIN)	SKBD23B30BKE16319
Ref. no.	7765

Basis	
Type	Drawbar
Aksel	3
Stand	Fine

Tyres	
% remaining	40/100 - 80/80 - 40/40
Dimensions	385/65x22,5

Dimensions	
Internal height mm	1120
Internal width mm	2400
Internal length mm	5120
Cubic meters	14,8

Brakes	
Drum brakes	✓
ABS	✓

Weight	
Loading capacity kg	18700
Overall weight kg	24000
Tare weight kg	5300
King pin kg	1000

Coupling	
Electrical coupling	EBS - 13 polet lysstik
Air-coupling	duromatic
Manufacturer	57 mm trækøje
V "KN air"	52
V "KN no air"	70
Coupling height mm	850

Suspension	
Air	✓
Chassis	
Total length mm	xxx
Hydraulic	✓
Shaft type	BPW
Axle load kg	8000 - 8000 - 8000
Truck body / box	
Bottom	pæn jævn
Tent	
Roll tilt	✓
Tippers	
3-way	✓
automatic tailgate	✓

Beskrivelse

Kelberg 3 axle tipper model D23B3

Interior dimensions approx. : Length: 5120 x Height: 1200 x Width: 2400 mm = 14.6m3 - 3-way tip
air-controlled 400 mm high automatic tailgate - roller tarpaulin - tip pistons look tight
BPW axles - Drum brakes - Air suspension - 385/65R22.5 tire mounting
57mm tow eye coupling height in 2 positions, currently the height is 850 can be changed down to 700 mm coupling height - coupling length xxx mm
LED taillights and 2 x 2 LED work lights on the side and rear.
EBS connector + 1 x 15 pin electrical connector - Duomatic air coupling - 1 conductor oil coupling

Chassis and cargo box in good condition according to year with gray undercarriage

Delivered with a new inspection from 13/8-2025 with the following preparation:
disassembly of brakes. through lubrication of s. keys. replacement of brake shoes on 1st and 3rd axle and installation of new brake drums 3rd axle. 2 anchor plate sets, installation of 2 used tires, new drawbars 3rd axle right side. replacement of spring bushes 1st axle both sides. reading of ebs fault memory. repair of loose connection in socket, 2 pcs. rear fender replaced

Contact Scanvo Trucks Danmark A/S +45 87 24 43 70 - or via email: salg@scanvo.dk

Visit our website www.scanvo.dk always more than 300 units in stock

Nye og brugte containere
Mere end 100 enheder!





