

Volvo FM420 8x2*6 Trippel NTM 25m3, Refuse collection



Scanvo Trucks Danmark A/S
Hårup Skovvej 7, Hårup
8600 Silkeborg

Sælger
Salgsafdeling
salg@scanvo.dk
+45 8724 4370
+45 3046 2148 / +45 2498 2148

Basis		Cab		Brakes	
Type	Truck	Cab type	Day cab	Disc brake	✓
Aksel	8x2*6	Mirror camera	✓	ABS	✓
Stand	Very fine	Equipment kit	komfort +	Engine brake	✓
Registration		Radio	✓	Suspension	
Model year	2016	Automatic air conditioning	✓	Front, air	✓
Reg. date	01-11-2016	Fahrhaus ausen		Rear, air	✓
Reg. no.	BE97309	Color	Traffic Blue RAL 5017	Weight	
Latest inspection	27-09-2024	Lightbox	✓	Loading capacity kg	14545
Chassis number (VIN)	YV2XTW0FXGA793461	Fog lights	✓	Overall weight kg	32000
Ref. no.	7826	extra spotlights	✓	Tare weight kg	16915
Engine and transmission		Blitz lights	✓	Compactor	
Engine	R6	Chassis		M3	25
Hp	420	Wheelbase mm	4600	municipal waste	✓
Km	500300	Axle load, front kg	9000	industrial waste disposal	✓
Gear box	I-shift	Axle load, rear kg	24000	Make	NTM
EURO type	6	Toolbox	✓	Type	KGH-HB
Number of tanks	1	Working light	✓	Chassis no.	20301
Litre of tank	330	Hydraulically steered rear axle	✓	Model year	2016
Rear axle, single interchange	✓	Liftable axles	2. + 4.	Winch	✓
PTO engine	✓	Tyres		Lift	✓
Adblue litre of tank	64	% remaining	50/50 - 100/60 - 100/100 - 100/40	Wiegereinrichtung	✓
Without clutch pedal	✓	Dimensions	385/55R22,5 - 385/55R22,5 - 315/70R22,5 - 385/55R22,5	1 champer	✓

Beskrivelse

Volvo FM420 Hk 8x2*6 Triple chassis waste disposal truck

NTM KGH - HB 1 chamber industrial waste disposal plant year 2016- 25 m3 - load cells under the box from Poul Tarp and printer in the cab - roof winch - lift for mini containers - tool / magazine box under construction

Lots of work lights facing backwards as well as rotating beacons and light signs on the roof and rear of the waste disposal plant

EURO 6 environmental engine - 330 ltr diesel tank - 64 ltr AD Blue tank - 4600 mm axle distance - full air suspension - I-Shift aut gearshift - hydraulically steerable 2nd + 4th axle both liftable

Day cab low entry - air conditioning - engine/cabin heater rear + cyclist camera - rear alarm - factory painted Traffic Blue RAL 5017

Appears in normal and functional condition according to the year and is continuously serviced last service performed 27/9-2024 at km. 461,433 oil change + gearbox + rear axle oil

Contact Scanvo Trucks +45 87244370 - or email salg@scanvo.dk

- AN OFFER YOU CAN'T REFUSE

See other refuse trucks on our website www.scanvo.dk + 300 other units











