

Scania P320 B 6x2*4 NB, Refuse collection



Scanvo Trucks Denmark A/S
Hårup Skovvej 7, Hårup
8600 Silkeborg

Sælger
Salgsafdeling
salg@scanvo.dk
+45 8724 4370
+45 3046 2148 / +45 2498 2148

Basis	
Type	Truck
Aksel	6x2*4
Stand	Very fine
Registration	
Model year	2018
Reg. date	03-10-2018
Reg. no.	CB79734
Latest inspection	30-09-2025
Chassis number (VIN)	YS2P6X20005508911
Ref. no.	8068
Cab	
Cab type	CP17 M-cab
Rear-view camera	✓
Radio	✓
Multifunction steering wheel	✓
Thermo	✓
Air suspension cab	✓
Automatic air conditioning	✓
Automatic disaster Brake (FCW)	✓
Chassis	
Wheelbase mm	3950
Axle load, front kg	8000
Axle load, rear kg	19000
Toolbox	✓
Working light	✓
Hydraulically steered rear axle	✓

Engine and transmission	
Engine	DC09 126/320 hp
Hp	320
Km	241200
Gear box	GA766 Allison+5 aut shift
EURO type	6
Number of tanks	1
Litre of tank	300
Rear axle, single interchange	✓
PTO engine	✓
PTO gearbox	✓
Adblue litre of tank	47
Without clutch pedal	✓

Fahrhaus ausen	
Warninglight	✓
Color	Blå metallic
Lightbox	✓
Fog lights	✓
extra spotlights	✓
Blitz lights	✓
LED front light	✓

Tyres	
% remaining	90/90 - 20/30 - 25/50
Dimensions	
385/55R22,5 - 315/70R22,5 - 385/55R22,5	
Brakes	
Disc brake	✓
ABS	✓
Suspension	
Front, air	✓
Rear, air	✓
Weight	
Overall weight kg	26000
Tare weight kg	17200
Compactor	
M3	ca 20
municipal waste	✓
industrial waste disposal	✓
Make	Rosroca - Dennis Eagle
Type	x
Chassis no.	x
Model year	2018
Lift	✓
Wiegeeinrichtung	✓
2 chambers	✓

Beskrivelse

Scania P320 6x2*4 NB

RosRoca / Dennis Eagle recycling plant - x m3 + xm3 m3 volume - 2 chambers for daily recycling at the rear from Terberg model TCH-OTL-LC - - lift for mini containers - load cells built into the box excl. IT system / weighing computer in the cab

Euro 6 - full air suspension - Allison automatic gearbox - hydraulically swivelling / lifting bogie axle - 3950mm axle distance

CP17 L cab with low entry - air conditioning - air-suspended cab - radio - LED headlights - flashers - light sign and extra high beams on the roof + in the front grille

Regularly serviced, last service at 241067 km oil change on engine and coolant + filter and gearbox oil - Appears in good and regular condition - **AN OFFER YOU CAN'T REFUSE**

Contact Scanvo +45 87244370 - email: salg@scanvo.dk

See more refuse trucks on our website www.scanvo.dk - Always more than 300 units in stock







