Volvo FM460 8x2*6 - FAUN 533L frontpress, Refuse collection



Scanvo Trucks Danmark A/S
Hårup Skovvej 7, Hårup
8600 Silkeborg

Sælger
Salgsafdeling
salg@scanvo.dk
+45 8724 4370
+45 3046 2148 / +45 2498 2148

Basis	
Type	Truck
Aksel	8x2*6
Stand	Very fine

Registration	
Model year	2018
Reg. date	31-10-2018
Reg. no.	CE19796
Chassis number (VIN)	YV2XTY0F4JA830202
Ref. no.	8086

Cab	
Cab type	Day cab
Mirror camera	✓
Rear-view camera	✓
Radio	✓
Automatic air conditioning	✓
Parking heater	✓

Tyres	
% remaining	60/80 - 80/60 - 90/90 - 90/90
Dimensions	385/55R22,5 - 385/55R22,5 - 315/70R22,5 - 315/70R22,5

Engine and transmission	
Hp	460
Km	319200
Gear box	Powertronic PT2606
EURO type	6
Number of tanks	1
Litre of tank	330
Rear axle, single interchange	✓
PTO engine	✓
Adblue litre of tank	64
Without clutch pedal	✓

Fahrhaus ausen	
Color	RAL 5017 Trafficv Blue
Fog lights	✓

Chassis	
Wheelbase mm	5100
Gear box cooler	✓
Working light	✓
Liftable axles	4.

Brakes	
Disc brake	✓
ABS	✓
Engine brake	VEB +

Suspension	
Front, air	✓
Rear, air	✓

Weight	
Overall weight kg	32000 / 35000
Tare weight kg	19730

Compactor	
M3	x
industrial waste disposal	✓
Make	FAUN
Type	FAUN 533L frontpress
Chassis no.	31533-18-400827
Model year	2018
Lift	✓
Wiegeeinrichtung	✓
1 champer	✓

Beskrivelse

Volvo FM460 hp 8x2*6 Tri-axle chassis refuse truck

FAUN 533L front-loading industrial refuse body (2018 model); load cells under the body; in-cab printer; front loader for containers; tool/storage box under the bodywork

Extensive rear-facing work lighting, plus rotating beacons and illuminated signs on the roof and at the rear of the refuse body

Euro 6 engine – 330L diesel tank – 64L AdBlue tank – 5100 mm wheelbase – full air suspension – Powertronic PT2606 automatic transmission – 4th axle steerable & liftable – VDS (Volvo Dynamic Steering)

Day cab with low entry – automatic climate control – reversing and cyclist cameras – reversing alarm – rear air-suspended cab – parking heater for short stops – factory-painted Traffic Blue (RAL 5017)


In good, functional condition consistent with its age; regularly serviced (most recent service: 27/09/2024 at 461,433 km, including oil, transmission fluid, and rear axle oil changes)

Can potentially be supplied as a chassis only

Contact Scanvo Trucks at +45 87244370 or email salg@scanvo.dk

View other refuse trucks on our website, www.scanvo.dk (over 300 other vehicles available)

SCANVO
TRUCKS DANMARK A/S

















NET:
BRUTTO
445
C
M
0
1
2
3
4
5
6
7
8
9




Drive
WB
Product type
Vehicle type
Volvo Truck Corporation
Kg
1
2
3
4
5











FAUN
FRONTPRESS


T 32000
NL 1 16.35


VOLVO
FM


FAUN
8.2.2 Vehicle layout/main components
Description
1 Collection container
2 Lift arm
3 Forks
4 Ejector plate
5 Rear section
6 Oil tank
7 Hydraulic pump
8 Telescopic cylinder
9 Hydraulic cylinder for tail section
10 Hydraulic cylinder for roof flap
11 Hydraulic cylinder for forks
12 Hydraulic cylinder for lift arms
13 Hydraulic cylinder for fork guide rotational movement
14 Side roof flaps
15 Push button on left, close tail section
16 2-hand operation, close tail section
17 Protective roof for driver's cab
18 Safety support, only on left
19 Locking bags
Fig. 1


Description
Fig. 1
8.2.8 Vehicle layout/main components
FAUN


7.2.10 Betjeningselementer
7.2.10.1 Oversigt

Fremstilling af billhovedkomponenter
Betegnelse
Fig. 1

6.8 Typeskilt