Scania L 360 B 6x2*4 LB 1 kammer indurtri, Refuse collection



Scanvo Trucks Danmark A/S
Hårup Skovvej 7, Hårup
8600 Silkeborg

Sælger
Salgsafdeling
salg@scanvo.dk
+45 8724 4370
+45 3046 2148 / +45 2498 2148

Basis	
Type	Truck
Aksel	6x2*4
Stand	Very fine

Registration	
Model year	2020
Reg. date	09-10-2020
Reg. no.	CV83763
Latest inspection	09-09-2026
Chassis number (VIN)	YS2L6X20005579383
Ref. no.	8103

Engine and transmission	
Engine	DC09 141/360 D01
Hp	360
Km	299000
Gear box	Opticruise GRSO905R aut shift
EURO type	6
Number of tanks	1
Litre of tank	350
Rear axle, single interchange	✓
PTO engine	✓
Adblue litre of tank	80
Without clutch pedal	✓

Chassis	
Wheelbase mm	4150
Axle load, front kg	8000
Axle load, rear kg	19000
Toolbox	✓
Hydraulically steered rear axle	✓
Liftable axles	3.

Cab	
Cab type	CL20 Low entry
Rear-view camera	✓
Engine cab heater	✓
Radio	✓
Walkie	✓
Navigation	✓
Lane-assistent	✓
Number of seats	3
Distance radar	✓
Cruise control	✓
Load Indicator	✓
Multifunction steering wheel	✓
Thermo	✓
Air suspension cab	✓
Bluetooth	✓
Automatic air conditioning	✓
Automatic disaster Brake (FCW)	✓
Electric windows	✓

Fahrhaus ausen	
Color	RAL 3003
Fog lights	✓
additional worklights	✓
LED front light	✓

Tyres	
% remaining	75 - 60 - 50
Dimensions	385/55R22,5 - 315/70R22,5 - 385/55R22,5

Brakes	
Disc brake	✓
ABS	✓
Retarder	✓

Suspension	
Front, air	✓
Rear, air	✓

Weight	
Loading capacity kg	9725
Overall weight kg	26000
Tare weight kg	16275

Compactor	
M3	23
industrial waste disposal	✓
Make	Rosroca
Type	Olympus 23W HCT
Chassis no.	316324
Model year	2020
Winch	✓
Wiegeeinrichtung	✓
1 champer	✓

Beskrivelse

Ros Roca / Phoenix refuse collection body – 23 m³ capacity – single-compartment unit for domestic and industrial waste
Model: Olympus 23W HCT (Serial No.: 316324)

Cable winch system for large containers

Integrated weighing system (body-mounted) with in-cab display and printer (excluding IT equipment)

Full air suspension – automatic transmission – retarder – 4,150 mm wheelbase

- AN OFFER YOU CAN'T REFUSE

Low-entry CL 20 cab – air conditioning – radio – engine/cab heater – strobe lights – illuminated sign – reversing camera – RAL 3003 Cardinal Red cab

In very good condition and fully serviced.
Last service (including oil change for engine, gearbox, and rear axle) performed at 298,000 km.
New brake pads on all three axles at 285,000 km.
Inspected/MOT valid until 09/09/2026.

Contact Scanvo at +45 87244370 – email: salg@scanvo.dk

View more refuse trucks on our website: www.scanvo.dk – Always over 300 units in stock.

SCANVO
TRUCKS DANMARK A/S













SCANVO
TRUCKS DANMARK A/S









